
Parking Lot guidance tree

Activities described in "Pavement Management Sites" (roadway resurfacing, mill and overlay, white topping, black topping, etc.) should be disregarded when assessing parking lots as most of these activities are considered routine maintenanceand do not meet the requirements of an "applicable development site". The common confusion in this matter is the language of "Areas primarily used for parking or access to parking are not roadways" and therefore cannot be considered a "Pavement Management Sites" and excluded from Post-construction requirements. Since these areas are not considered roadways then activities performed must meet the requirements of an "applicable development site" when determining Post-construction requirements.



Parking Lot Guidance Tree Purpose: This tree offers guidance on determining whether a parking lot can be considered routine maintenance.

See Also:

Interpretative Fact Sheet - Routine Maintenance Decision Tree

Permit References (Permit Modification 4):

Part I.E.3 – "Construction Activity", particularly note the sentences describing routine maintenance. Page 17 (COR090000), Page 18 (COR080000).

Part I.E.4 – "Applicable development sites" and "Redevelopment", Page 26 (COR090000), Page 27-28 (COR080000).

Part I.E.4.a.i. – Excluded Sites: Pavement Management Sites. Page 27. COR090000 Part I.E.4.c.i., Page 28. COR080000